

Photos documenting development/construction of the Imperial River Company RV Park in Maupin OR. This was built in a designated FEMA floodplain area with no floodplain development permit. The land accommodated a pair of Osprey for many years. The old nest was cut down to allow for development after the pair returned in the spring. Although a new one was eventually installed, the birds did not nest or produce eggs, as construction proceeded adjacent to the nest during nesting season. This land was also habitat for many deer and other wildlife.

Figure 1 Jan 2021 Showing Vegetation/Trees Along River

Figure 2 Jan 2021 Showing Vegetation/Trees Along River

Figure 3 Feb 2022 Excavator Pulling Vegetation/Trees from River and Burning Vegetation

Figure 4 Feb 2022 Excavator Pulling Vegetation/Trees from River

Figure 5 Feb 2022 Burning Vegetation/Trees Pulled from River – Removal of vegetation on adjacent upriver property, owned by McLucas Family

Figure 6 Feb 2022 After Vegetation/Trees Removed and Burned – Building Burning – including upriver property owned by McLucas Family, cleared of vegetation in/along river

Figure 7 Feb 2023 After Removal of Vegetation/Trees From River – 1 year later

Figure 8 Jan 2024 High Water

Figure 9 Jan 2024 High Water - Close up of Survey Marker below old Osprey Nest

Figure 10 May 22 2024 – Old Osprey nest removed – new one installed at property marker

Figure 11 May 2024 During Construction – After Osprey nest removed – New nest installed closer to river – upriver McLucas Property

Figure 12 May 2024 During Construction

Figure 13 June 13 2024 During Construction

Figure 14 Oct 9 2024 Completed Development

Figure 15 Oct 9 2024 Completed Development

Figure 16 Oct 9 2024 - Development area previously provided vital habitat for wildlife, deer, birds, etc.

Figure 17 Oct 29 2024 Compacted gravel trail below berm

Figure 18 Oct 29 2024 Compacted gravel trail below berm

Figure 19 Oct 29 2024 Compacted gravel trail – destruction of vegetation

Figure 20 Oct 29 2024 Destruction of vegetation along compacted gravel trail

Figure 21 Oct 29 2024 Destruction of vegetation

Figure 22 2019 High Water

Figure 23 2019 High Water



Figure 1 Jan 2021 Showing Vegetation/Trees Along River



Figure 2 Jan 2021 Showing Vegetation/Trees Along River



Figure 3 Feb 2022 Excavator Pulling Vegetation/Trees from River and Burning Vegetation



Figure 4 Feb 2022 Excavator Pulling Vegetation/Trees from River



Figure 5 Feb 2022 Burning Vegetation/Trees Pulled from River – Removal of vegetation on adjacent upriver property, owned by McLucas Family



Figure 6 Feb 2022 After Vegetation/Trees Removed and Burned – Building Burning – including upriver property owned by McLucas Family, cleared of vegetation in/along river



Figure 7 Feb 2023 After Removal of Vegetation/Trees From River – 1 year later



Figure 8 Jan 2024 High Water



Figure 9 Jan 2024 High Water Close up of Survey Marker below old Osprey Nest



Figure 10 May 22 2024 – Old Osprey nest removed – new one installed at property marker



4

Figure 11 May 2024 During Construction – After Osprey nest removed – New nest installed closer to river – upriver McLucas Property



Figure 12 May 2024 During Construction

